


For giving supply to **Mr. Indraj Kesthap Singh** of **Mr. Rajm Harash Singh** - LINE CHART  
 Add **Will Gulawali** **8100K Paha** **Mahmudabad** **Sitapur**  
 for **0.5** HP Load and **0.5** Process

- 1- Total length of line ..... HT.
- 2- No of Support ..... **80 (cont)** ..... LT.
- 3- No of Stay ..... **02** ..... PCC.
- 4- No of earthing ..... **2** .....
- 5- Capacity of T/F ..... **2** .....
- 6- Increasing capacity  Kva  kva

*[Signature]*  
 JUNIOR ENGINEER

*[Signature]*  
 SUB-DIVISIONAL OFFICER



*[Signature]*  
 JUNIOR ENGINEER

*[Signature]*  
 SUB-DIVISIONAL OFFICER

| No. | Span | HT  | LT   | PCC | Capacity | Remarks |
|-----|------|-----|------|-----|----------|---------|
| 1   | 100  | 330 | 1100 |     | 200A     |         |
| 2   | 100  | 330 | 1100 |     | 200A     |         |
| 3   | 100  | 330 | 1100 |     | 200A     |         |
| 4   | 100  | 330 | 1100 |     | 200A     |         |
| 5   | 100  | 330 | 1100 |     | 200A     |         |
| 6   | 100  | 330 | 1100 |     | 200A     |         |
| 7   | 100  | 330 | 1100 |     | 200A     |         |
| 8   | 100  | 330 | 1100 |     | 200A     |         |
| 9   | 100  | 330 | 1100 |     | 200A     |         |
| 10  | 100  | 330 | 1100 |     | 200A     |         |

Abb No - 1008126230